



APS Inspection Service
1582 Victoria Ave
Lakewood, OH 44107

Commercial Inspection Report



8611 Detroit Ave
Cleveland, Ohio 44102



Cut Floor Joist



Whole knocked in the block



Mold



Wood rot in the floor joist



Mold and wood rot



Block and brick veneer



Wood rot



Foundation Cracks



Foundation Cracks



Broken side walks



Foundation Holes



Broken Block



Foundation Slab cracks



Joints show settlement



Stress cracks



Stress cracks



Stress cracks



Stress Cracks



Stress Cracks



Stress Cracks



Stress Cracks



Stress Cracks



Asbestos Tile



Stress Cracks




Stress Cracks



Stress Cracks



Stress Cracks



The drainage may be the problem with the slab cracks





Trees are up-rooting pavement.



Moisture in the walls




Light shows moisture in the walls on the high side of the meter.




Moisture in the walls



Stress Cracks




Stress Cracks




Stress Cracks With Displacement



Stress Cracks in the slab with moisture



Stress Cracks



Stress Cracks

APS Inspection Service

20:18 April 22, 2008

Page 8 of 8
Sample Commercial Picture Report.alb5

